ISO 13856-2:2013-04 (E)

Safety of machinery - Pressure-sensitive protective devices - Part 2: General principles for design and tes ting of pressure-sensitive edges and pressure-sensitive bars

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Requirements for design and testing 7
4.1 Effective sensing surface 7
4.2 Actuating force for testing 9
4.3 Pre-travel 10
4.4 Working travel 10
4.5 Overtravel 10
4.6 Force .....

travel relationships 10
4.7 Minimum operating speed 12
4.8 Number of operations 12
4.9 Sensor output 13
4.10 Response of output signal switching device to actuating force 13
4.11 Reset function 13
4.12 Environmental conditions 14
4.13 Power supply variations 15
4.14 Electrical equipment 15
4.15 Hydraulic equipment 16
4.16 Pneumatic equipment 16
4.17 Enclosure 16
4.18 Additional coverings for sensors 17
4.19 Access 17
4.21 Adjustments 18
4.22 Sensor fixing and mechanical strength 18
4.23 Recovery after deformation 18
4.24 Connections 19
4.25 Sharp corners, sharp edges and rough surfaces 19
4.26 Mechanical features 19
4.27 Inhibition and blocking 19

5 Marking 19

6 Information for selection and use 20
6.1 General 20
6.2 Essential data for the selection of suitable pressure-sensitive edge or pressure-sensitive bar 20
6.3 Information for use 21

7 Verificationofrequirements 23

7.1 General 23
7.2 Test samples 24
7.3 Test pieces 24
7.4 Test No. 1 -- Safety-related data for selection, installation, commissioning, operation and maintenance of suitable pressure-sensitive edges or pressure-sensitive bars 25
7.5 Test No. 2 -- Mounting orientations of sensors 25
7.6 Test No. 3 -- Actuating force 26
7.7 Test No. 4 -- Force .....

travel relationship(s) 32
7.8 Test No. 5 -- Number of operations 32
7.9 Test No. 6 -- Output state of sensor and output signal switching device 33
7.10 Test No. 7 -- Response of output signal switching device to actuating force, reset and state of power supply 33
7.11 Test No. 8 -- Environmental conditions 33
7.12 Test No. 9 -- Power supply variation 35
7.13 Test No. 10 -- Electrical, hydraulic and pneumatic equipment 36
7.14 Test No. 11 -- Enclosure 36
7.15 Test No. 12 -- Additional coverings for sensors 36
7.16 Test No. 13 -- Access 36
7.18 Test No. 15 -- Adjustments 37
7.19 Test No. 16 -- Sensor fixing and mechanical strength 37
7.20 Test No. 17 -- Recovery after deformation 37
7.21 Test No. 18 -- Connections 37
7.22 Test No. 19 -- Sharp corners, sharp edges and rough surfaces 37
7.23 Test No. 20 -- Mechanical features 37
7.24 Test No. 21 -- Inhibition and blocking 38
7.25 Test No. 22 -- Marking 38
7.26 Test No. 23 -- Information for selection and use 38

Annex A (normative) Timing diagrams for pressure-sensitive edges/bars with/without reset 39

Annex B (informative) Operating speed, force and travel -- Explanatory remarks and recommendations 43

Annex C (informative) Device selection guidance for machinery manufacturer/user 46

Annex D (informative) Design guidance 48

Annex E (informative) Application guidance 51

Annex F (informative) Guidance on commissioning and testing after installation 52

Bibliography 55