ISO 15202-1:2000-02 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 1: Sampling

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Principle 5

5 Requirement 5

6 Sampling equipment 5

7 Occupational exposure assessment 7

8 Sampling method 9

9 Documentation 12

Annex A (informative) Guidance on filter selection 14

Annex B (informative) Temperature and pressure correction for the indicated volumetric flow rate 16

Bibliography 17