DIN EN 14031:2021-09 (E)

Workplace exposure - Quantitative measurement of airborne endotoxins

Contents

Page

European foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Requirements 6
4.1 Skills needed for sampling 6
4.2 Sampling 7
4.2.1 General 7
4.2.2 Equipment 7
4.2.3 Filters 7
4.3 Sample transport 7
4.4 Sample storage at the laboratory 8
4.5 Glassware 8
4.6 Extraction liquids, water and detergents 8
4.7 Test for contamination 8
4.8 Sampling documentation 8

5 Extraction 9
5.1 General 9
5.2 Equipment 9
5.3 Procedure 9
5.4 Storage conditions 10
5.5 Documentation of extraction 10

6 Analytical method 10
6.1 General 10
6.2 Equipment 11
6.3 Procedure 11
6.3.1 Measurement 11
6.3.2 Calibration 11
6.3.3 Calculation 11
6.4 Validation 12
6.5 Documentation of analysis 12

7 Expression of results 12

8 Precision 13

9 Test report 13

Annex A (informative) Properties of endotoxins and sources of occupational exposure 14

Annex B (informative) Principle of LAL-assays 17

Annex C (informative) Deposition of endotoxins on inner sampler walls 19

Bibliography 20