ISO 24095:2021-09 (E)

Workplace air - Guidance for the measurement of respirable crystalline silica

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 2

5 Analytical quality requirements 3

6 Administrative controls 3

7 Sampling 4
7.1 General 4
7.2 Sampler 4
7.3 Filters and foams 4
7.4 Sampling flow measurement devices and pumps 5
7.5 Sampling period 5
7.6 Transportation 6

8 Procedures 7
8.1 Handling of filter cassettes 7
8.2 Method validation 7
8.3 Calibration 7
8.4 Sample preparation 8
8.5 Sample measurement 9
8.5.1 Limit of Detection 9
8.5.2 X-ray diffraction 9
8.5.3 Infrared analysis 9
8.6 Instrumental variation 10
8.6.1 X-ray diffraction 10
8.6.2 Infrared analysis 10

9 Internal quality control 10

10 Externalverificationandassessmentofuncertainty 11

11 Test report 11
11.1 Minimum report requirements 11
11.2 Data to be archived by the laboratory 12

Annex A (informative) Polymorphs of crystalline silica and their interferences 13

Annex B (informative)ThequantificationofcristobaliteusingX-raydiffraction 19

Annex C (informative) Example of quality control charting for respirable crystalline silica 23

Annex D (informative) Estimation of expanded uncertainty for measurements of respirable crystalline silica 25

Annex E (informative) Differences between samplers (cyclones and other types) 35

Annex F (informative)Useofproficiencytestdatatoevaluatetheperformanceof XRDand IR methods in the presence of interferences 37

Bibliography 42