ISO 11174:2023-05 (E)

Workplace air - Determination of particulate cadmium and cadmium compounds - Flame and electrothermal atomic absorption spectrometric method

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Principle 2

5 Reactions 3

6 Requirement 3

7 Reagents 3

8 Apparatus 5

9 Sampling 8
9.1 Sampling procedure 8
9.1.1 Collection characteristics and flow rate 8
9.1.2 Sampling period 8
9.1.3 Temperature and pressure effects 8
9.2 Preparation of sampling equipment 9
9.3 Collection of samples 9
9.4 Transportation 10

10 Procedure for analysis 10
10.1 Cleaning of glassware and polypropylene bottles 10
10.2 Preparation of sample solutions and blank test solutions 11
10.3 Analysis by flame atomic absorption spectrometry 11
10.3.1 General 11
10.3.2 Preparation of calibration solutions 12
10.3.3 Calibration 12
10.3.4 Determination 12
10.4 Analysis by electrothermal atomic absorption spectrometry 13
10.4.1 General 13
10.4.2 Preparation of working calibration solutions 13
10.4.3 Calibration and determination 13
10.5 Estimation of the instrumental detection limit 15

11 Expression of results 15
11.1 Calculations 15
11.2 Performance of the method 16
11.3 Detection limit and working range 17

12 Special cases 18

13 Test report 18

Annex A (informative) Typical operating parameters for determination of cadmium by electrothermal atomic absorption spectrometry 20

Bibliography 21