ISO 22578-2:2024-02 (E)

Graphical symbols - Safety colours and safety signs - Part 2: Measurement of photopic luminance of phosphorescent components used in a natural disaster safety way guidance system

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Testspecification 1
4.1 Test specimens 1
4.2 Conditioning 2
4.3 Ambient conditions 2
4.4 Irradiance, illuminance and luminance instrumentation 2
4.4.1 Irradiance instrumentation 2
4.4.2 Illuminance instrumentation 2
4.4.3 Luminance instrumentation 3
4.5 Excitation light conditions 3
4.6 Luminance measurements 3
4.6.1 General 3
4.6.2 Telephotometer method 3
4.6.3 Contact method 3
4.6.4 Luminance recordings 4
4.7 Test report 4
4.8 Marking of phosphorescent materials 5

Bibliography 6