DIN EN 15051-1:2026-01 (E)

Workplace exposure - Measurement of the dustiness of bulk materials - Part 1: Requirements and choice of test methods

Contents

Page

European foreword 3

Introduction 4

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Principle 7

5 General procedures 7
5.1 Schematic overview of the procedure 7
5.2 Conditioning of the bulk material 8
5.2.1 As-received condition 8
5.2.2 Conditioning specifications 9
5.3 Sample and environmental control 9
5.4 Taking samples from the bulk material 9
5.5 Moisture content 10
5.6 Bulk density 10
5.7 Test procedure 10
5.8 Replicate tests 10
5.9 In-house test powder 10
5.10 Reporting 10

6 Test methods 10
6.1 Description of the methods 10
6.2 Selection of the most appropriate test method 11

7 Evaluation of dustiness 11

8 Test report 12

Annex A (normative) Determination of moisture content 13

Annex B (normative) Determination of bulk density of the test material 15

Annex C (informative) Spheriglass 5000 CP00 - An example of a suitable powder for quality purposes 16

Bibliography 17