ISO 15202-3:2004-11 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inducti vely coupled plasma atomic emission spectrometry - Part 3: Analysis

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 2

3 Terms, definitions and abbreviated terms 2
3.1 General definitions 2
3.2 Analytical definitions 3
3.3 ICP-AES definitions 4
3.4 Statistical terms 7

4 Principle 8

5 Requirements 8

6 Reagents 8

7 Laboratory apparatus 12

8 Procedure 13
8.1 Method development 13
8.2 Instrument performance checks 18
8.3 Routine analysis 18
8.4 Estimation of detection and quantification limits 19
8.5 Quality control 20
8.6 Measurement uncertainty 21

9 Expression of results 21

10 Method performance 22
10.1 Method detection limits and quantification limits 22
10.2 Upper limits of the analytical range 23
10.3 Bias and precision 23
10.4 Overall uncertainty of sampling and analysis methods 23
10.5 Spectral interferences 24

11 Test report 24
11.1 Test records 24
11.2 Laboratory report 25

Annex A (informative) Guidance on maintenance of ICP-AES instrumentation 26

Annex B (informative) Examples of performance checks and fault diagnostics 28

Annex C (informative) Procedure for quality control and identification (QUID) of malfunctions of inductively coupled plasma atomic emission spectrometers 29

Annex D (informative) Recalculation of metal and metalloid in air concentrations to reference conditions 35

Bibliography 36