DIN EN 482:2006-10 (E)

Workplace atmospheres - General requirements for the performance of procedures for the measurement of chemical agents

Contents

Page

Foreword 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 7

4 Classification 9
4.1 General 9
4.2 Screening measurements of time weighted average concentration 9
4.3 Screening measurements of variation of concentration in time and/or space 9
4.4 Measurements for comparison with (occupational exposure) limit values and periodic measurements 9

5 Performance requirements 10
5.1 Screening measurements of time weighted average concentration 10
5.2 Screening measurements of variation of concentration in time and/or space 10
5.3 Measurements for comparison with limit values and periodic measurements 10
5.4 Composite procedures 11
5.5 Transport and storage 11
5.6 Environmental conditions 11
5.7 Description of measuring procedure 12
5.8 Dimension of result 12
5.9 Additional requirements 12

6 Test method 12

7 Validation report 13

Annex A (informative) Measurement categories described in EN 689 and involving a combination of measurement tasks 14

A.1 Worst case measurements 14
A.2 Fixed point measurements 14
A.3 Short-term peak measurements 14

Annex B (informative) Structure of a method description 15

Annex C (informative) Calculation of uncertainty of measurement 16

C.1 General 16
C.2 Uncertainty associated with sampled air volume 16
C.2.1 Pumped sampling 16
C.2.2 Diffusive sampling 18
C.3 Uncertainty associated with sampling efficiency 18
C.3.1 Pumped sampling methods for gases and vapours 18
C.3.2 Diffusive sampling methods for vapours 18
C.3.3 Aerosol sampling methods 19

C.4 Uncertainty associated with sample storage and transportation 21
C.4.1 Sample storage 21
C.4.2 Transportation 21
C.5 Uncertainty associated with analytical recovery 21
C.5.1 Gases and vapours 21
C.5.2 Measurement of chemical agents in airborne particles 23
C.6 Uncertainty associated with analytical variability 24
C.6.1 General 24
C.6.2 Estimation using repeatability data 24
C.6.3 Estimation using within-laboratory reproducibility data 25
C.6.4 Blank subtraction 26
C.7 General equation for combination of uncertainty components 26

Bibliography 27