# ISO 15530-3:2011-10 (E)

## Geometrical product specifications (GPS) - Coordinate measuring machines (CMM): Technique for determining the uncertainty of measurement - Part 3: Use of calibrated workpieces or measurement standards

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Normative references ..... 1

3 Terms and definitions ..... 1

4 Symbols ..... 2

5 Requirements ..... 3
5.1 Operating conditions ..... 3
5.2 Similarity conditions ..... 3

6 Principle of the uncertainty evaluation using calibrated workpieces ..... 4

7 Procedure ..... 4
7.1 Measuring equipment ..... 4
7.2 Execution ..... 4
7.3 Calculation of the uncertainty ..... 5
7.4 Applying the substitution method: special considerations ..... 9

8 Reverification of the measurement uncertainty ..... 9

9 Interim check of the measurement uncertainty ..... 10

Annex A (informative) Examples of application ..... 11

Annex B (informative) Relation to the GPS matrix model ..... 16

Bibliography ..... 18