ISO 1502:1996-02 (E)

ISO_general-purpose metric screw threads_- Gauges and gauging

Contents

Page

1 Scope **1**

2 Normative references **1**

3 Symbols and abbreviations **1**

4 Types of gauges **3**

4.1 Gauges for external threads of workpieces and their check plugs and setting plugs **3**

4.2 Gauges for internal threads of workpieces **3**

5 Gauging of workpieces **3**

5.1 Gauging of external threads **3**

5.2 Gauging of internal threads **4**

5.3 Inspection gauging **4**

6 Reference temperature **4**

7 Function, checking and use of gauges **4**

7.1 Gauges for external threads of workpieces and their check plugs and setting plugs **5**

7.2 Gauges for internal threads of workpieces **8**

8 Tolerance zones for the diameters of gauges (see figures 1 and 2) **8**

9 Tolerance zones for plain gauges (see figures 3 and 4) **11**

10 Thread profiles for gauges **13**

10.1 Profiles with complete flanks (see figures 5 and 6) **13**

10.2 Profiles with truncated flanks (see figures 7 and 8) **16**

10.3 Displacement of the clearance groove for a profile with truncated flanks **18**

11 General features of screw gauges **19**

11.1 Gauges for external threads of workpieces **19**

11.2 Gauges for internal threads of workpieces **19**

11.3 Blunt start of thread **19**

12 Tolerances and permissible wear for pitch diameters of gauges (see tables 4 to 9) **21**

13 Formulae for calculation of gauge limits **23**

13.1 Screw gauges for external threads of workpieces **23**

13.2 Plain gauges for the major diameters of external threads of workpieces **23**

13.3 Screw gauges for internal threads of workpieces **23**

13.4 Plain gauges for the minor diameters of internal threads of workpieces **23**

Annex

A Bibliography **27**