ISO 7066-2:1988-07 (E)

Assessment of uncertainty in the calibration and use of flow measurements devices; part 2: non-linear calibration relationships

Contents

Page

0 Introduction 1

1 Scope and field of application 1

2 References 1

3 Definitions 1

4 Symbols and abbreviations 1

5 Curve fitting 2
5.1 General 2
5.2 Computational methods 3
5.3 Selecting the Optimum degree of fit 3

6 Uncertainty 4

Annexes

A Regression methods 5

B Orthogonal polynomial curve fitting 9

C Computer program using orthogonal polynomials 11

D Examples 17

E Finite-difference method 27