ISO 29864:2007-12 (E)

Self adhesive tapes — Measurement of breaking strength and elongation at break

Contents

page

Foreword 3

Introduction 4

1 Scope 5

2 Terms and definitions 5

3 Significance and use 5

4 Principle 5

5 Apparatus 6

6 Test sample and test pieces 7

7 Procedure 7

8 Expression of results 8

9 Test report 8