DIN EN 16424:2015-03 (E)

Characterization of waste - Screening methods for the element composition by portable X-ray fluorescence instruments

Contents

Page

Foreword 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Principle 5

5 Safety remarks 6

6 Apparatus and equipment 6
6.1 X-ray fluorescence spectrometer 6
6.2 Direct measurement using a hand-held instrumentation in direct contact with the sample 7
6.3 Hand-held instrumentation mounted on a stand using sample cups filled with the sample 7
6.4 Portable bench top XRF instrument 7
6.5 Spoon, stamp and/or hammer 7
6.6 Mortar and pestle 7
6.7 Thin-film support 7
6.8 Sample cups 7

7 Calibration 7
7.1 General 7
7.2 Interferences 8
7.3 Calibration procedure 8
7.4 Validation of the calibration 9

8 Screening strategy 10

9 Sample preparation 12
9.1 General 12
9.2 Sample preparation for direct measurement 12
9.3 Sample preparation for filling cups 12
9.4 Sample preparation for heterogeneous samples 12

10 Analysis 12
10.1 General 12
10.2 Direct in situ measurement (hand-held method) 12
10.3 Measurement by using a mounted hand-held XRF instrument or a small portable closed XRF instrument 13

11 Calculation of the result 13

12 Assessment of the XRF screening measurement 13
12.1 General 13
12.2 Identification of the presence or absence of the elements under investigation 13
12.3 Indication of the concentration range of the elements under investigation 14

13 Quality control 14
13.1 Drift correction procedure 14
13.2 Blank test 14
13.3 Reference materials 14

14 Test report 15

Annex A (informative) Examples of instrumentation 16

Annex B (informative) List of analytical lines and spectral line overlaps 19

Annex C (informative) Evaluation of the acceptance criteria 20

C.1 Uncertainty 20
C.2 Test of the absence of an element 20
C.3 Test of the documented concentration of an element 20
C.4 Estimation of uncertainty 21

Annex D (informative) Validation 22

Bibliography 33