ISO 22125-1:2019-11 (E)

Water quality - Technetium-99 - Part 1: Test method using liquid scintillation counting

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms,definitionsandsymbols 2

4 Principle 3

5 Sampling and storage 4

6 Procedure 4
6.1 Sample preparation for measurement 4
6.2 Sample measurement 5

7 Quality assurance and quality control program 5
7.1 General 5
7.2 Variables that could influence the measurement 5
7.3 Instrument verification 5
7.4 Contamination 5
7.5 Interference control 5
7.6 Method verification 5
7.7 Demonstration of analyst capability 6
7.8 Sample measurement 6

8 Expression of results 6
8.1 Sample activity, recovery and uncertainties 6
8.2 Decision threshold 8
8.3 Detection limit 9
8.4 Confidence interval limits 9
8.5 Calculation using the activity per unit of volume 9
8.6 Conversion of activity concentration to mass concentration 10
8.7 Conversion of mass concentration to volume unit 10

9 Test report 10

Annex A (informative) Method 1 -- TEVA resin 12

Annex B (informative) Method 2 -- TRU resin 15

Annex C (informative) Method 3 -- Anion exchange resin 18

Bibliography 20