ISO/IEC TR 24720:2008-06 (E)

Information technology - Automatic identification and data capture techniques - Guidelines for direct part marking (DPM)

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Abbreviated terms 2

5 Overview of DPM 2
5.1 DPM methods 2
5.2 Reasons for utilizing DPM 3

6 Marking method selection 3

7 Marking methods 6

8 Cleaning 6

9 Marking surface preparation 6
9.1 Assessment 6
9.2 Protective coatings 7

10 Human readable marking 8
11 Symbol quality 8
12 Reading and grading DPM symbols 9
13 Verification 9
13.1 General 9
13.2 Configuration 9
13.3 Possible equipment setup 10
14 Imagers for direct part marking applications 11
14.1 General description 11
14.2 Fixed-mount imagers 11
14.3 Presentation imager 12
14.4 Hand-held imager 12

Annex A (informative) Intrusive marking methods 14

A.1 Intrusive marking 14
A.2 Re-marking requirements using intrusive marking methods 15
A.3 Laser marking 15
A.4 Dot peen marking 18
A.5 Other Intrusive marking methods 20

Annex B (informative) Non-intrusive marking methods 22

B.1 Non-intrusive marking methods 22
B.2 Ink jet marking 22

B.3 Fabric embroidery/weaving 25
B.4 Forge, cast 26
B.5 Laser bonding 27
B.6 Laser engineered net shaping (LENS) 27
B.7 Screen printing 28
B.8 Stencil 29

Annex C (informative) Rockwell Hardness 30

Bibliography 32