ISO/IEC 29121:2009-02 (E)

Information technology - Digitally recorded media for information interchange and storage - Data migration method for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Test methods 3
4.1 Test parameters 3
4.2 Test Drive 3
4.2.1 Test drive calibration 3
4.2.2 Test preparation 4
4.2.3 Test execution 4
4.3 Test area 4

5 Test result evaluation 4
5.1 Initial performance test result evaluation 4
5.2 Periodical performance test result evaluation 5

6 Test frequency 6

7 Prevention of deterioration 6

Annex A (informative) Causes of deterioration for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks ... 7

A.1 Deterioration 7
A.2 Disk structure 7
A.3 Causes of deterioration 7
A.4 Nature of deterioration 8
A.5 Effects of deterioration 8

Annex B (informative) Recommendations on handling, storage and cleaning conditions for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks 9

B.1 Handling 9
B.2 Storage 9
B.3 Cleaning 10

Annex C (informative) Relation between BER and PIE SUM 8 11

Annex D (informative) Normalization of the time scales 12

Annex E (informative) Test area 14

Bibliography 15