DIN EN 16602-70-61:2023-01 (E)

Space product assurance - High-reliability soldering for surface mount, mixed technology and hand-mounted electrical connections; English version EN 16602-70-61:2022

Contents

Page

European Foreword..13

Introduction..14

1 Scope..21

2 Normative references..22

3 Terms, definitions and abbreviated terms..24

- 3.1 Terms from other standards..24
- 3.2 Terms specific to the present standard..24
- 3.3 Abbreviated terms..29
- 3.4 Nomenclature..31

4 Principles of reliable soldered connections..32

5 Preparatory conditions..33

- 5.1 Facility cleanliness..33
- 5.2 Environmental conditions..33
- 5.3 Lighting requirements..34
- 5.4 Precautions against static discharges..34
  - 5.4.1 Overview..34
  - 5.4.2 General..35
  - 5.4.3 ESD Protected Area..35
  - 5.4.4 Precautions against ESD during manufacturing..36
  - 5.4.5 Protective packaging and ESD protection..37
- 5.5 Equipment and tools..37
  - 5.5.1 General..37
  - 5.5.2 Brushes..38
  - 5.5.3 Cutters and pliers..38
  - 5.5.4 Bending tools..39
  - 5.5.5 Clinching tools..39
  - 5.5.6 Insulation strippers..40
  - 5.5.7 Hot air blower..41

5.5.8 Soldering tools 41
5.5.9 Baking and curing ovens 42
5.5.10 Solder deposition equipment 43
5.5.11 Automatic component placement equipment 43
5.5.12 Dynamic wave-solder machines 43
5.5.13 Selective wave solder equipment 44
5.5.14 Reflow process equipment 45
5.5.15 Depanelization tool 47
5.5.16 Cleanliness testing equipment 47
5.5.17 Optical microscope 47
5.5.18 Automatic Optical Inspection (AOI) equipment 47
5.5.19 X-ray inspection equipment 47

6 Material selection 49

6.1 General 49
6.2 Solder 49
6.2.1 Form 49
6.2.2 Composition 50
6.2.3 Storage and handling of paste purity 52
6.3 Fluxes 52
6.3.1 Rosin based fluxes 52
6.4 Solvents 53
6.5 Flexible insulation materials 54
6.6 Terminals 54
6.6.1 Materials 54
6.6.2 Tin, silver, and gold-plated terminals 54
6.7 Wires 55
6.8 Sculptured flex 55
6.9 Printed circuits substrates 55
6.9.1 Substrates selection 55
6.9.2 Gold finish on PCBs footprint 55
6.9.3 PCB design requirements for wave and selective wave soldering 56
6.10 Components 56
6.10.1 General 56
6.10.2 Moisture sensitive components 57
6.11 Adhesives, potting, underfill and conformal coatings 57

7 Preparations prior to mounting and soldering 58

7.1 General handling 58
7.2 Storage 58
    7.2.1 Components 58
    7.2.2 PCBs 58
    7.2.3 Materials requiring segregation 58
7.3 Baking conditions of PCBs 59
7.4 Baking and storage of moisture sensitive components 59
7.5 Preparation of components, wires, terminals, and solder cups 60
    7.5.1 Damage to insulation 60
    7.5.2 Damage to conductors and braid 60
    7.5.3 Cleaning before soldering 61
    7.5.4 Insulation clearance 61
    7.5.5 Wire lay 61
7.6 Degolding and pretinning 61
    7.6.1 General 61
    7.6.2 Solder baths method for degolding and pretinning of components terminations and terminals 62
    7.6.3 Solder iron method for degolding and pretinning 64
    7.6.4 Pretinning processes 64
7.7 Preparation of the soldering tip 65

8 Components mounting requirements prior to soldering 67

8.1 General requirements 67
8.2 Mounting of through hole components 67
    8.2.1 General 67
    8.2.2 Heavy components 68
    8.2.3 Metal-case components 68
    8.2.4 Glass-encased components 68
    8.2.5 Stress relief of components with bendable leads 68
    8.2.6 Stress relief of components with non-bendable leads 71
    8.2.7 Bending of component leads 72
    8.2.8 Lead attachment to PCBs 73
    8.2.9 Mounting of through hole connectors to PCBs 76
    8.2.10 Mounting of swage terminals to PCBs 77
    8.2.11 Mounting of components to terminals 78
8.3 Mounting of surface mount components 79
    8.3.1 General 79
    8.3.2 Lead forming 80

8.3.3 Inspection of solder paste deposition 80

9 Attachment of conductors to terminals, solder cups and cables 81

9.1 General 81
9.2 Wire termination 81
    9.2.1 Breakouts from cables 81
    9.2.2 Insulation clearance 82
9.3 Turret and straight-pin terminals 82
9.4 Bifurcated terminals 83
    9.4.1 General 83
    9.4.2 Bottom route 83
    9.4.3 Side route 84
    9.4.4 Top route 85
    9.4.5 Combination of top and bottom routes 86
    9.4.6 Combination of side and bottom routes 86
9.5 Hook terminals 86
9.6 Pierced terminals 87
9.7 Solder cups for connector 87
9.8 Insulation sleeving 88
9.9 Wire and cable interconnections 89
    9.9.1 General 89
    9.9.2 Preparation of wires 89
    9.9.3 Preparation of shielded wires and cables 90
    9.9.4 Pre-assembly of wires 90
9.10 Connection of wires to PCBs 91
9.11 Connection of coaxial cables to PCBs 93

10 Assembly to terminals and to PCBs 94

10.1 Overview 94
10.2 General soldering conditions 94
    10.2.1 General 94
    10.2.2 Positioning 95
    10.2.3 Application of flux 96
    10.2.4 Flux controls for wave-soldering equipment 97
    10.2.5 Soldering temperatures 97
    10.2.6 Soldering of conductors in terminals 99
10.3 Soldering of components, terminals, and wires into PCB through holes 100
    10.3.1 General 100

10.3.2 Solder fillets for wires and terminations 100
10.3.3 Solder fillets for component leads in plated or non-plated through holes 101
10.4 Soldering of surface mount components 102
10.4.1 General 102
10.4.2 Rectangular and square end-capped or end-metallized leadless chip 104
10.4.3 Cylindrical and square end-capped components with cylindrical or oval body 106
10.4.4 Bottom terminated chip components 107
10.4.5 L-Shape inwards components 109
10.4.6 Leadless component with plane termination 110
10.4.7 Leaded component with plane termination 110
10.4.8 Leadless castellated ceramic chip carrier components 112
10.4.9 No lead Quad Flat Pack 113
10.4.10 Flat pack and gull-wing leaded components with round, rectangular, ribbon leads 115
10.4.11 Components with “J” leads 116
10.4.12 Components with ribbon terminals without stress relief 117
10.4.13 Stacked modules components with leads protruding vertically from bottom 119
10.4.14 Area array devices 120
10.5 Rework and repair 122
10.5.1 Removal of solder on unpopulated PCB 122
10.5.2 Rework, repair and modifications 122
10.6 High-voltage connections 123
10.7 Solderless components 125

11 Post soldering process requirements 126

11.1 Cleaning of PCB assemblies 126
11.1.1 General 126
11.1.2 Verification of cleanliness 127
11.1.3 Surface Insulation Resistance (SIR) testing 127
11.1.4 Sodium chloride (NaCl) equivalent ionic contaminants testing 128
11.1.5 Monitoring of cleanliness 129
11.2 Staking and bonding 129
11.3 Conformal coating, potting and underfill 130

12 Final inspection 132

12.1 General 132
12.2 Visual acceptance criteria 132

12.3 Visual rejection criteria 133
12.4 X-ray rejection criteria 135
12.5 Warp and twist of populated boards 136
12.6 Inspection records 136

13 Verification procedure 137
13.1 Verification approval procedure 137
  13.1.1 Request for verification 137
  13.1.2 Technology sample 137
  13.1.3 Audit of assembly processing 138
  13.1.4 Verification programme documentation 138
  13.1.5 Verification samples and testing 139
  13.1.6 Final verification review 140
  13.1.7 Approval status of assembly line 140
  13.1.8 Withdrawal of approval status 141
13.2 Verification programme 141
  13.2.1 General 141
  13.2.2 Verification for PTH manual soldering 147
  13.2.3 Additional verification for wave soldering 147
  13.2.4 Soldering log 147
13.3 Special verification testing for ceramic area array components 149
  13.3.1 General 149
  13.3.2 Evaluation of AAD capability samples 151
  13.3.3 Electrical verification of AAD assembly 151
13.4 Assembly verification with electrical testing procedure 152
13.5 Verification programme with reduced temperature range 155
13.6 Verification for solderless process 156
13.7 Conditions for delta verification 158
13.8 Verification by similarity 160
  13.8.1 General conditions for similarity 160
  13.8.2 Conditions for similarity for PTH components 160
  13.8.3 Conditions for similarity for SMD 161
  13.8.4 Conditions for similarity for solderless components 164

14 Environmental tests conditions 165
14.1 Overview 165
14.2 Visual inspection 165
14.3 X-ray inspection 165

14.4 Cleanliness test 165
14.5 Warp and twist of PCB 165
14.6 Electrical continuity measurement 166
14.7 Electrical continuity for wave soldered multilayers PCB 166
14.8 Vibration 167
14.9 Mechanical shock 169
14.10 Damp heat test 171
14.11 Temperature cycling test 171
14.12 Temperature cycling test with reduced temperature range 172
14.13 Life test 174
14.14 Final visual inspection 174
14.15 Microsection 175
  14.15.1 Microsection facilities 175
  14.15.2 Microsections location 175
  14.15.3 Microsection acceptance criteria 176
  14.15.4 Microsection acceptance criteria for ceramic chip capacitors 189
14.16 Anomalies in PCB and sculptured flex during verification 196

15 Outsourcing 197
15.1 General 197

16 Process identification document (PID) 199
16.1 Overview 199
16.2 Document preparation 199
16.3 Approval 199
16.4 Contact person 199
16.5 Process identification document update 199

17 Quality assurance 200
17.1 General 200
17.2 Data 200
17.3 Nonconformance 200
17.4 Calibration 200
17.5 Traceability 201
17.6 Workmanship standards 201
17.7 Inspection points 201
17.8 Operators, inspectors and instructors training and certification 201

Annex A (normative) Verification programme - DRD 203
A.1 DRD identification 203

A.2 Expected response 203

Annex B (normative) Verification report - DRD 205

B.1 DRD identification 205

B.2 Expected response 205

Annex C (normative) Process Identification Documentation (PID) - DRD 207

C.1 DRD identification 207

C.2 Expected response 207

Annex D (normative) Assembly Summary Table - DRD 210

D.1 DRD identification 210

D.2 Expected response 210

Annex E (normative) Visual workmanship standards for through hole component 212

E.1 Soldered stud terminals 212

E.2 Soldered turret terminals 213

E.3 Soldered bifurcated terminals 215

E.4 Soldered hook terminals 216

E.5 Soldered cup terminals 217

E.6 Miscellaneous examples of soldered wires 218

E.7 Soldered wire to shielded cable interconnections 219

E.8 Assembly of Dual in Line Package 221

Annex F (informative) Visual and X-ray workmanship standards for SMDs 222

F.1 Workmanship illustrations for standard SMDs 222

F.2 X Ray Workmanship illustrations for solder flow and voids 238

F.3 X Ray Workmanship illustrations for ball grid array devices 239

F.4 Workmanship illustrations for column grid array devices 240

Annex G (informative) Example of an SMT audit report 242

Annex H (informative) Solder Alloys melting temperatures and choice 251

H.1 Melting temperatures and choice 251

Bibliography 252

Figures

Figure 5-1: Profile of correct cutters for trimming leads 39

Figure 5-2: Example of suitable mechanical strippers 40

Figure 8-1: Assembly of TO-39 and CKR06 70

Figure 8-2: TO package with underfill 70
Figure 8-3: Methods for incorporating stress relief with components having bendable leads 71
Figure 8-4: Methods for attaching wire extensions to non-bendable leads 72
Figure 8-5: Minimum lead bend 73
Figure 8-6: Stud leads 74
Figure 8-7: Wires used to connect opposite sides of a PCB 75
Figure 8-8: Clinching with stress relief for component in non-plated hole 76
Figure 8-9: Types of terminal swaging 78
Figure 8-10: Method of stress relieving components attached to terminals 78
Figure 8-11: Exposed element 79
Figure 9-1: Side route connections to turret terminals 83
Figure 9-2: Bottom route connections to bifurcated terminal 84
Figure 9-3: Side-route connection to bifurcated terminal 85
Figure 9-4: Top route connection to bifurcated terminal 85
Figure 9-5: Connections to hook terminals 86
Figure 9-6: Connections to pierced terminals 87
Figure 9-7: Connections to solder cups (connector type) 88
Figure 9-8: Methods for securing wires 91
Figure 9-9: Connection of solid or stranded wires to PCBs 92
Figure 9-10: Connection of coaxial cables to PCBs 93
Figure 10-1: Maximum tilt for assembled PTH component 96
Figure 10-2: Maximum tilt for assembled SMD component 96
Figure 10-3: Minimum acceptable wetting on component side 102
Figure 10-4: Mounting of rectangular and square end-capped and end-metallized components 104
Figure 10-5: Mounting of cylindrical end-capped components 106
Figure 10-6: Mounting of square end-capped components 107
Figure 10-7: Mounting of bottom terminated chip component 108
Figure 10-8: Mounting of components with “L-shape inwards” leads 109
Figure 10-9: Mounting of leadless component with plane termination 110
Figure 10-10: Mounting of leaded components with plane termination 111
Figure 10-11: Mounting of leadless castellated ceramic chip carrier components 112
Figure 10-12 Mounting of QFN 114
Figure 10-13: Mounting of gull-wing leaded components with round, rectangular, ribbon leads 115
Figure 10-14: Mounting of component with “J” leads 116
Figure 10-15: Mounting of components without stress relief 117

Figure 10-16: Mounting of stacked module components with leads protruding vertically from bottom 119
Figure 10-17: Typical configuration of ceramic grid array component 120
Figure 10-18: High voltage connection 124
Figure 10-19: Solderless assembly configuration 125
Figure 13-1 : Generic soldering verification flow 146
Figure 13-2: Example of soldering log for joints discrepancy log 148
Figure 13-3: Area Array component verification programme flow chart 150
Figure 13-4: Assembly verification with electrical testing procedure 154
Figure 13-5: Verification procedure for solderless technology 157
Figure 14-1:Vibration test flow chart 167
Figure D-1 : Example of component type preparation and mounting configuration 211
Figure E-1 : Soldered stud terminals 212
Figure E-2 : Soldered turret terminals with single conductors 213
Figure E-3 : Soldered turret terminals with twin conductors 214
Figure E-4 : Soldered bifurcated terminals 215
Figure E-5 : Soldered hook terminals 216
Figure E-6 : Soldered cup terminals 217
Figure E-7 : Examples of unacceptable soldered wires 218
Figure E-8 : Hand soldered wire to shielded cable interconnections 219
Figure E-9 : Hand soldered wire to shielded wire interconnections 220
Figure E-10 : Hand soldered wire interconnections - details of defects 221
Figure F-1 : Examples of acceptable and not acceptable solder flow through and maximum voids during X-ray 238
Figure F-2 : Angled-transmission X-radiograph showing solder paste shadow due to partial reflow: Reject 239
Figure F-3 : Perpendicular transmission X-radiograph showing unacceptable defects 239
Figure F-4 : Perpendicular transmission X-radiograph showing non-wetted footprint 240
Figure F-5 : X-radiograph of CGA mounted on PCB showing solder bridge: Reject 240
Figure F-6 : X-radiograph of CGA showing solder fillets at base of columns: acceptable 241

Tables

Table 5-1: Particle concentrations classes 8 till 9 according to ISO 14644-1 (2015) 34
Table 5-2: EPA requirements summary 36
Table 6-1: Chemical composition of spacecraft solders 51
Table 6-2: Fluxes 53
Table 7-1: Clearances for insulation 61
Table 7-2: Solder baths parameters for degolding and pretinning 63

Table 8-1: Dimensions and tolerances for clinching component in non-plated hole 76

Table 9-1: Dimensions for connections of solid or stranded wires to PCBs...........................92

Table 9-2: Dimensions for connections of coaxial cables to PCBs.......................................93

Table 10-1: Dimensional and solder fillet for rectangular and square end capped components 105

Table 10-2: Dimensional and solder fillet for cylindrical end-capped components..............106

Table 10-3: Dimensional and solder fillet for square end-capped components 107

Table 10-4: Dimensional and solder fillet for bottom terminated chip components.............108

Table 10-5: Dimensional and solder fillet for “L-shape inwards” components 109

Table 10-6: Dimensional and solder fillet for leadless component with plane termination ...110

Table 10-7: Dimensional and solder fillet for leaded components with plane termination....111

Table 10-8: Dimensional and solder fillet for leadless castellated ceramic chip carrier components 112

Table 10-9: Dimensional and solder fillet for QFN components 114

Table 10-10: Dimensional and solder fillet for gull-wing leaded components with round, rectangular, ribbon leads...115

Table 10-11: Dimensional and solder fillet for components with “J” leads...........................116

Table 10-12: Dimensional and solder fillet for components with ribbon terminals without stress relief...117

Table 10-13: Dimensional and solder fillet for stacked module components with leads protruding vertically from bottom 119

Table 10-14: Dimensional and solder fillet for area array devices......................................120

Table 13-1: Conditions invoking verification..159

Table 14-1: Modal survey conditions 168

Table 14-2: Minimum severity for sine vibration testing 168

Table 14-3: Minimum severity for random vibration testing...169

Table 14-4: Shock sensitive electronic components vs. failure modes (Table reproduced from ECSS-E-HB-32-25A)...170

Table 14-5: Component microsection location and acceptance criteria 178

Table 14-6: Acceptance criteria for internal defects in ceramic chip capacitors after microsectioning 191