ISO 8642:2025-07 (E)

Aerospace - Self-locking nuts with maximum operating temperature greater than 425 °C - Test methods

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Inspections and tests 1
4.1 Hardness test 1
4.1.1 Procedure 1
4.1.2 Method 2
4.2 Bearing surface squareness test 2
4.2.1 Test device 2
4.2.2 Method 3
4.3 Axial load test 4
4.3.1 Test device 4
4.3.2 Method 4
4.4 Wrenching feature test 5
4.4.1 General 5
4.4.2 Test device 5
4.4.3 Method 6
4.5 Torque-out test 6
4.5.1 General 6
4.5.2 Test device 7
4.5.3 Method 7
4.6 Test of no rotation of the captive washer 8
4.6.1 General 8
4.6.2 Test device 8
4.6.3 Method 8
4.7 Push-out test 8
4.7.1 General 8
4.7.2 Test device 9
4.7.3 Method 9
4.8 Self-locking torque at ambient temperature 10
4.8.1 Test device 10
4.8.2 Method 11
4.9 Self-locking torque at ambient temperature after heat soak at maximum operating temperature 12
4.9.1 Test device 12
4.9.2 Method 14
4.10 Permanent set test 15
4.10.1 General 15
4.10.2 Test device 15
4.10.3 Method 16
4.11 Vibration test 17
4.11.1 General 17
4.11.2 Test device 17
4.11.3 Method 19
4.12 Swaging test 20
4.12.1 General 20

4.12.2 Visual examination 20

Bibliography 21