ISO 14952-3:2003-11 (E)

Space systems - Surface cleanliness of fluid systems - Part 3: Analytical procedures for the determination of no nvolatile residues and particulate contamination

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Acceptance inspection 2
4.1 General 2
4.2 Visual inspection 2
4.3 Acidity and alkalinity test 2
4.4 Acceptance inspection of items cleaned in a controlled environment 2
4.5 Acceptance inspection of items cleaned in the field 6
4.6 Acceptance inspection of packaging materials 7
4.7 Acceptance inspection of items by functional test 9

5 Sampling and analytical practices 9
5.1 Cleanliness level test methods 9
5.2 Microscopic particle population 12
5.3 Gravimetric NVR analysis method 12
5.4 Aqueous ultrasonic sampling and total carbon (TC) NVR analysis 13

Annex A (informative) Sensitivity factor calculation 15