ISO 4666-4:2007-08 (E)

Rubber, vulcanized - Determination of temperature rise and resistance to fatigue in flexometer testing - Part 4: Consta nt-stress flexometer

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Principle 2

5 Apparatus 2

6 Test piece 8

7 Test conditions 8

8 Procedure 9

9 Precision 13

10 Test report 14

Annex A (informative) Precision 15

Annex B (informative) Guidance for using precision results 18

Bibliography 19