DIN 50969-1:2009-06 (E)

Prevention of hydrogen-induced brittle fracture of high-strength steel building elements - Part 1: Advice on the prevention

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 General 5

3 Measures to be taken at the design and manufacturing stages 5
3.1 Design measures 5
3.2 Material-related measures 5
3.3 Manufacture-related measures 6
3.4 Minimizing residual tensile stresses 6

4 Coating process 6
4.1 General 6
4.2 Pretreatment for activation of the surface for subsequent coatings 7
4.3 Coating 7
4.4 Heat treatment after coating 7

Bibliography 8