ISO 9717:2010-12 (E)

Metallic and other inorganic coatings - Phosphate conversion coating of metals

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Information to be supplied by the purchaser to the processor 3
4.1 Essential information 3
4.2 Additional information 3

5 Designation 3
5.1 General 3
5.2 Designation specifications 4
5.3 Designation of heat treatment requirements 4
5.4 Classification of phosphate conversion coating 5

6 Requirements 6
6.1 Surface preparation 6
6.2 Phosphate conversion coating 6
6.3 Processing after phosphating 6
6.4 Thickness of coating 7
6.5 Stress-relief heat treatment before cleaning and phosphating 8
6.6 Hydrogen-embrittlement-relief heat treatment after phosphating 8
6.7 Treatments for supplementary coatings 8
6.8 Adhesion of phosphate conversion coatings 9
6.9 Quality-evaluation test of phosphate conversion coatings 9

7 Sampling 9

Annex A (informative) Methods of application, characteristics and significance of phosphate conversion coatings 10

Annex B (informative) Determination of rinse-water contamination 13

Annex C (informative) Identification of phosphate conversion coating 15

Annex D (normative) Salt droplet test 17

Annex E (normative) Determination of resistance of phosphate conversion coating to neutral salt spray (fog) test 20

Annex F (normative) Treatments for supplementary coating 22

Bibliography 23