# ISO 10863:2011-09 (E)

## Non-destructive testing of welds - Ultrasonic testing - Use of time-of-flight diffraction technique (TOFD)

## Contents

Page


Foreword ..... iv

1 Scope ..... 1

2 Normative references ..... 1

3 Terms and definitions ..... 2

4 General remarks on the capabilities of the technique ..... 2

5 Testing levels ..... 3

6 Information required prior to testing ..... 3
6.1 Items to be defined by specification ..... 3
6.2 Specific information required by the operator before testing ..... 4
6.3 Written test instruction or procedure ..... 4

7 Requirements for personnel and equipment ..... 4
7.1 Personnel qualifications ..... 4
7.2 Equipment ..... 5

8 Preparation for testing ..... 5
8.1 Volume to be inspected ..... 5
8.2 Setup of probes ..... 6
8.3 Scan increment setting ..... 6
8.4 Geometry considerations ..... 6
8.5 Preparation of scanning surfaces ..... 6
8.6 Temperature ..... 7
8.7 Couplant ..... 7
8.8 Provision of datum points ..... 7

9 Testing of base material ..... 7

10 Range and sensitivity settings ..... 8
10.1 Settings ..... 8
10.2 Checking of the settings ..... 8
10.3 Reference blocks ..... 9

11 Weld testing ..... 10

12 Interpretation and analysis of TOFD images ..... 10
12.1 General ..... 10
12.2 Assessing the quality of the TOFD image ..... 10
12.3 Identification of relevant TOFD indications ..... 11
12.4 Classification of relevant TOFD indications ..... 11
12.5 Determination of location and size ..... 12
12.6 Evaluation against acceptance criteria ..... 13

13 Test report ..... 13

Annex A (informative) Reference blocks ..... 15

Annex B (informative) Examples of TOFD scans ..... 20

Bibliography ..... 30