ISO 7539-6:2011-10 (E)

Corrosion of metals and alloys - Stress corrosion testing - Part 6: P reparation and use of precracked specimens for tests under constant load or constant displacement

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Principle 4

5 Specimens 5
5.1 General 5
5.2 Specimen design 6
5.3 Stress intensity factor considerations 17
5.4 Specimen preparation 22
5.5 Specimen identification 23

6 Initiation and propagation of fatigue cracks 23

7 Procedure 25
7.1 General 25
7.2 Environmental considerations 25
7.3 Environmental chamber 26
7.4 Environmental control and monitoring 27
7.5 Determination of KISCC by crack arrest 28
7.6 Determination of KISCC by crack initiation 31
7.7 Measurement of crack velocity 32

8 Test report 33

Annex A (normative) Use of notched specimens for stress corrosion tests 35

Annex B (normative) Determination of crack growth velocity 38