ISO/TR 13115:2011-12 (E)

Non-destructive testing - Methods for absolute calibration of acoustic emission transducers by the reciprocity technique

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Preparation for calibration 3
4.1 Transfer medium and calibration signal 3
4.2 Mounting of acoustic emission transducer 4
4.3 Calculation of reciprocity parameters 5

5 Method for three-transducer calibration 6
5.1 Apparatus to be used 6
5.2 Method of measurement 6
5.3 Method for determination of absolute sensitivity 9

6 Method for two-transducer calibration 9
6.1 Apparatus to be used 10
6.2 Method of measurement 10
6.3 Method for determination of absolute sensitivity 10

7 Method for impulse response calibration 11
7.1 Apparatus to be used 11
7.2 Method of measurement 11
7.3 Method for determination of frequency response 13
7.4 Method for determination of impulse response 15

8 Method for representing calibration results 16
8.1 Representation items for calibration results 16
8.2 Method for representing frequency response of absolute sensitivity 16
8.3 Method for representing impulse response of absolute sensitivity 17

Bibliography 18