ISO 11039:2012-02 (E)

Surface chemical analysis - Scanning-probe microscopy - Measurement of drift rate

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitionsandabbreviatedterms 1
3.1 Termsanddefinitions 1
3.2 Abbreviated terms 2

4 Measurement method 2

5 Requirements 3
5.1 Instrument requirements 3
5.2 Environment requirements 3

6 Measurement procedures 3
6.1 Initial check 3
6.2 Basic characterization and the settling time 4
6.3 Further characterization and fresh image areas 5
6.4 Other specimens 7

7 Measurement report 7

Annex A (normative) Image correlation method 8

Annex B (normative) Characteristic-marker method 11

Annex C (normative) Non-periodic grating method 13

Annex D (informative) Guidance to users 16

Annex E (informative) Instrumental parameters to consider to reduce drift rates 17

Annex F (informative) Example of drift results and analysis 18

Bibliography 19