ISO 13588:2012-10 (E)

Non-destructive testing of welds - Ultrasonic testing - Use of automated phased array technology

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Testing levels 2

5 Information required prior to testing 4
5.1 Itemstobedefinedpriortoproceduredevelopment 4
5.2 Specificinformationrequiredbytheoperatorbeforetesting 4
5.3 Written test procedure 4

6 Requirements for personnel and equipment 5
6.1 Personnelqualifications 5
6.2 Equipment 5

7 Preparation for testing 5
7.1 Volume to be inspected 5
7.2 Verificationoftestset-up 6
7.3 Scan increment setting 6
7.4 Geometry considerations 6
7.5 Preparation of scanning surfaces 6
7.6 Temperature 6
7.7 Couplant 6

8 Testing of base material 7

9 Range and sensitivity settings 7
9.1 Settings 7
9.2 Checking of the settings 8
9.3 Reference blocks 8

10 Equipment checks 9

11 Procedurequalification 9

12 Weld testing 9

13 Data storage 10

14 Interpretation and analysis of phased array data 10
14.1 General 10
14.2 Assessing the quality of the phased array data 10
14.3 Identificationofrelevantindications 10
14.4 Classificationofrelevantindications 10
14.5 Determination of location and length of an indication 11
14.6 Indication assessment 11
14.7 Evaluation against acceptance criteria 11

15 Test report 11

Annex A (informative)Typicalreferenceblocksandreferencereflectors 13

Bibliography 17