DIN EN 16016-3:2012-12 (E)

Non destructive testing - Radiation methods - Computed tomography - Part 3: Operation and interpretation

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Operational procedure 5
4.1 General 5
4.2 CT system set-up 5
4.2.1 General 5
4.2.2 Geometry 5
4.2.3 X-ray source 6
4.2.4 Detector 6
4.3 Reconstruction parameters 7
4.4 Visualisation 7
4.5 Analysis and interpretation of CT images 7
4.5.1 General 7
4.5.2 Feature testing/defect testing 7
4.5.3 Dimensional testing 8

5 Requirements for acceptable results 10
5.1 Image quality parameters 10
5.1.1 Contrast 10
5.1.2 Noise 12
5.1.3 Signal to noise ratio 12
5.1.4 Contrast to noise ratio 12
5.1.5 Spatial resolution 13
5.2 Suitability of testing 15
5.3 CT examination interpretation and acceptance criteria 15
5.4 Records and reports 15
5.5 Artefacts 16
5.5.1 General 16
5.5.2 Beam hardening artefacts 16
5.5.3 Edge artefacts 17
5.5.4 Scattered radiation 18
5.5.5 Instabilities 18
5.5.6 Ring artefacts 18
5.5.7 Centre of rotation error artefacts 19
5.5.8 Motion artefacts 20
5.5.9 Artefacts due to an insufficient number of projections 21
5.5.10 Cone beam artefacts 21

Annex A (informative) Spatial resolution measurement using line pair gauges 23

A.1 Line pair gauges 23
A.2 Principle of measurement 24

Bibliography 27