DIN 25457-4:2013-04 (Englisch)

Activity measurement methods in the clearance of radioa ctive substances and components of nuclear facilities - Part 4: Contaminated and activated metal scrap

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Clearance strategy and preliminary examination 5
4.1 Specification of clearance strategy 5
4.2 Principles of preliminary examination 6
4.3 Spatial distribution of activity 8
4.4 Radionuclide mixture 8
4.5 Key nuclides and scaling factors and use of summation rule 8
4.6 Nuclide vector 9
4.7 Effects of decontamination 10

5 Method of decision measurement 10
5.1 General 10
5.2 Measurement of surface activity 12
5.3 Collimated in-situ gamma spectrometry 13
5.3.1 General 13
5.3.2 Field of application 13
5.3.3 Requirements for the measurement set-up for measurements on packages 15
5.3.4 Calibration 15
5.3.5 Performance of measurements 16
5.4 Activity measurement after smelting 17
5.4.1 General 17
5.4.2 Determination of activity 17
5.5 Measurement of total gamma activity 17

6 Documentation 18
6.1 General 18
6.2 Preliminary examination 19
6.3 Decision measurement 20

Annex A (normative) Averaging quantities for decision procedures 22

A.1 General 22
A.2 Averaging mass in decision procedures 22
A.3 Averaging area in decision procedures 22

Annex B (informative) Examples of nuclide vectors 24

Annex C (informative) Examples for the calculation of scaling factors when results are available for a set of samples 26

Annex D (informative) Partitioning factors of significant radionuclides when smelting metals with respect to product metal (smelt), slag and dust 30

Annex E (informative) Examples for the calculation of minimum thickness to convert area- related activity to mass-related activity 31

Bibliography 32