ISO 9513:2012-12 (E)

Metallic materials - Calibration of extensometer systems used in uniaxial testing

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Termsanddefinitions 1

3 Symbols and designations 1

4 Principle 2

5 Calibration equipment 2
5.1 Calibration apparatus 2
5.2 Calibration traceability 2

6 Pre-calibration inspection 2
6.1 Objective 2
6.2 Records of the inspection 3
6.3 Identificationofextensometersystemelements 3

7 Measurement of extensometer gauge length 3
7.1 Fixed gauge length extensometry 3
7.2 Variable gauge length extensometry 3
7.3 Non-contacting extensometry 4
7.4 Extensometer gauge lengths established using setting gauges 4

8 Calibration process 4
8.1 Environmental considerations 4
8.2 Position of the extensometer 4
8.3 Calibration increments 4
8.4 Calibration process 6
8.5 Determination of the characteristics of the extensometer system 6

9 Classificationoftheextensometersystem 7
9.1 Input data 7
9.2 Analysis of the data 7
9.3 Classificationcriteria 7
9.4 Assessment of the results 7

10 Uncertainty determination 8
10.1 Uncertainty of the calibration 8
10.2 Uncertainty budget determination 8

11 Extensometer system calibration intervals 8

12 Calibrationcertificate 8
12.1 Mandatory information 8
12.2 Data presentation 9

Annex A (informative) Uncertainty of measurement 10

Annex B (informative) Calibration of the calibration apparatus 15

Annex C (informative) Example of a report of the calibration of calibration apparatus 17

Annex D (informative)Examplesofextensometersystemconfigurations 20

Annex E (informative) Laser extensometry 29

Annex F (informative) Video extensometry 37

Annex G (informative)Fullfieldstrainmeasurementvideoextensometry 41

Annex H (informative) Calibration of a cross-head measurement system 43

Bibliography 44