ISO 17636-1:2013-01 (E)

Non-destructive testing of welds - Radiographic testing - Part 1: X- and gamma-ray techniques with film

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols and abbreviated terms 3

5 Classification of radiographic techniques 3

6 General preparations and requirements 4
6.1 Protection against ionizing radiation 4
6.2 Surface preparation and stage of manufacture 4
6.3 Location of the weld in the radiograph 4
6.4 Identification of radiographs 4
6.5 Marking 4
6.6 Overlap of films 4
6.7 Types and positions of image quality indicators 4
6.8 Evaluation of image quality 5
6.9 Minimum image quality values 5
6.10 Personnel qualification 6

7 Recommended techniques for making radiographs 6
7.1 Test arrangements 6
7.2 Choice of tube voltage and radiation source 12
7.3 Film systems and metal screens 13
7.4 Alignment of beam 15
7.5 Reduction of scattered radiation 15
7.6 Source-to-object distance 15
7.7 Maximum area for a single exposure 18
7.8 Density of radiograph 18
7.9 Processing 18
7.10 Film viewing conditions 19

8 Test report 19

Annex A (normative) Recommended number of exposures which give an acceptable examination of a circumferential butt weld 21

Annex B (normative) Minimum image quality values 26

Bibliography 30