ISO 12110-1:2013-07 (E)

Metallic materials - Fatigue testing - Variable amplitude fatigue testing - Part 1: General principles, test method and reporting requirements

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Principle of test 4
4.1 Control signal generation 4
4.2 Overview of test procedure 4

5 Original loading time history 5
5.1 General 5
5.2 Data filtering 5

6 Loading time history description 6
6.1 General 6
6.2 Time history sequences description 6
6.3 Cycle counting description 6

7 Programmed blocks 7

8 Transition matrix and generation of control signal from the matrix 7
8.1 Establishment of the matrix 7
8.2 Reconstruction of the loading signal 8
8.3 Control signal simplification 9

9 Conducting fatigue testing under variable amplitude conditions 9

10 Test report for each individual specimen 10
10.1 General 10
10.2 Original loading description 10
10.3 Testing conditions 10
10.4 Preliminary analysis of test data for each specimen and for a series of specimens 12

Annex A (informative) Standard loading time histories 18

Annex B (informative) Example of loading signal reconstruction by random draw in the transition matrix 19

Annex C (informative) Preliminary analysis of test data on a single specimen 21

Bibliography 24