ISO 8300:2013-12 (E)

Nuclear fuel technology - Determination of plutonium content in plutonium dioxide of nuclear grade quality - Gravimetric method

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Principle 1

3 Interferences 1

4 Apparatus 1

5 Procedure 2
5.1 Handling of the sample at the sampling station 2
5.2 Tarring of crucibles 2
5.3 Sub-sampling 2
5.4 Heating 2
5.5 Additional measurements 2

6 Expression of result 3
6.1 Calculation of the gravimetric conversion factor 3
6.2 Calculation of impurity correction factor 3
6.3 Calculation of plutonium concentration 3
6.4 Repeatability 4
6.5 Systematic errors 4

7 Test report 4

Annex A (informative) Gravimetric conversion factor for the non-volatile impurities 5