ISO 17859:2015-09 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Measurement method of piezoelectric strain at high electric field

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions, and symbols 1
3.1 Terms and definitions 1
3.2 Symbols 2

4 Measuring environment 2

5 Specimens 2
5.1 General 2
5.2 Shape and size 3
5.3 Electrodes 3
5.4 Polarization 3

6 Principle 3

7 Measurement equipment 3
7.1 Equipment 3
7.2 Components of equipment 4
7.3 Environment of specimen holder 5
7.4 Calibration of measurement equipment 5

8 Measurement conditions 5

9 Measurement procedures 5

10 Calculations and results 6

11 Test report 6

Annex A (informative) Example of reference sample 8