ISO 18554:2016-03 (E)

Surface chemic al analysis - Electron spectroscopies - Procedures for identifying, estimating and correcting for unintended degradation by X-rays in a material undergoing analysis by X-ray photoelectron spectroscopy

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Termsanddefinitions 1

3 Symbols and abbreviated terms 1

4 Sample degradation 2
4.1 Causes of degradation 2
4.2 Sample degradation 3
4.3 Measurements for identifying, and correcting for, degradation 3
4.3.1 Recognition of degradation 3
4.3.2 The first survey scan 3
4.3.3 The detail scans 4
4.3.4 The final survey scan 4
4.3.5 Inverting the order of acquisition for unstable compounds 4
4.3.6 Check for degradation 4
4.3.7 Deduce the undegraded intensity 4
4.4 Assessing the likelihood of degradation 6
4.4.1 Determining the value of AZ 6
4.5 Reporting degradation 6
4.6 Suggested procedures for minimising degradation 6
4.7 Influence of contamination 7
4.7.1 Contamination formation during spectrum acquisition 7
4.7.2 Reporting contamination 7

Annex A (informative) Materials reported to degrade during analysis 8

Annex B (informative) Examples of degradation 9

Annex C (informative) Compensation for formation of a contamination layer 14

Bibliography 16