ISO 17640:2017-10 (E)

Non-destructive testing of welds - Ultrasonic testing - Techniques, testing levels, and assessment

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Symbols 2

5 Principle 3

6 Information required prior to testing 3
6.1 Items to be specified 3
6.2 Specific information required before testing 3
6.3 Written test procedure 4

7 Requirements for personnel and equipment 4
7.1 Personnel qualifications 4
7.2 Test equipment 4
7.3 Probe parameters 4
7.3.1 Test frequency 4
7.3.2 Angles of incidence 4
7.3.3 Element size 5
7.3.4 Adaptation of probes to curved scanning surfaces 5
7.3.5 Coupling media 5

8 Testing volume 5

9 Preparation of scanning surfaces 6

10 Parent metal testing 6

11 Range and sensitivity setting 7
11.1 General 7
11.2 Reference for sensitivity setting 8
11.3 Evaluation levels 9
11.4 Transfer correction 9
11.5 Signal-to-noise ratio 9

12 Testing levels 9

13 Testing techniques 10
13.1 General 10
13.2 Manual scan path 10
13.3 Testing for imperfections perpendicular to the testing surface 10
13.4 Location of discontinuities 10
13.5 Evaluation of indications 10
13.5.1 General 10
13.5.2 Maximum echo amplitude 10
13.5.3 Discontinuity length 11

13.5.4 Discontinuity height 11
13.5.5 Characterization of discontinuities 11

14 Test report 11

Annex A (normative) Testing levels for various types of welded joints 13

Bbliography 29