ISO 5398-3:2018 (E)

Leather — Chemical determination of chromic oxide content — Part 3: Quantification by atomic absorption spectrometry

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Principle

5 Sampling and sample preparation

6 Reagents

6.1 Reagents for wet oxidation method
6.2 Reagents for atomic absorption spectrometry

7 Apparatus

8 Methods

8.1 Preparation of analytical solution
8.1.1 Wet oxidation method
8.1.2 Microwave digestion method
8.2 Measurement of the aqueous solution
8.2.1 General
8.2.2 Preparation of calibration graph
8.2.3 Analysis of the test solution

9 Calculation and expression of results

10 Test report

Annex A (informative) Determination of water and other volatile matter

Annex B (informative) Suitable atomic absorption spectrometry (AAS) equipment

Page count: 6