ISO 7539-6:2018 (E)

Corrosion of metals and alloys — Stress corrosion testing — Part 6: Preparation and use of precracked specimens for tests under constant load or constant displacement

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Principle

5 Specimens

- 5.1 General
- 5.2 Specimen design
- 5.3 Stress intensity factor considerations
- 5.4 Specimen preparation
- 5.5 Specimen identification

6 Initiation and propagation of fatigue cracks

7 Procedure

- 7.1 General
- 7.2 Environmental considerations
- 7.3 Environmental chamber
- 7.4 Environmental control and monitoring
- 7.5 Determination of KISCC by crack arrest
- 7.6 Determination of KISCC by crack initiation
- 7.7 Measurement of crack velocity

8 Test report

Annex A (informative) Use of notched specimens for stress corrosion tests

- A.1 General
- A.2 Symbols
- A.3 Principle
- A.4 Specimens
- A.4.1 General
- A.4.2 Specimen design
- A.4.3 Stress considerations
- A.4.4 Specimen preparation
- A.5 Procedure
- A.6 Test report

Annex B (informative) Determination of crack growth velocity

Page count: 44