ISO 4666-4:2018 (E)

Rubber, vulcanized — Determination of temperature rise and resistance to fatigue in flexometer testing — Part 4: Constant-stress flexometer

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Principle

5 Apparatus

- 5.1 Anvils
- 5.2 Oscillator
- 5.3 Displacement detector
- 5.4 Load detector
- 5.5 Heating chamber and temperature controller
- 5.6 Needle-type temperature detector
- 5.7 Temperature-detector position controller
- 5.8 Computer control unit
- 5.9 Measuring gauge

6 Calibration

7 Test piece

8 Test conditions

9 Procedure

- 9.1 General test procedure
- 9.2 Determination of fatigue life
- 9.2.1 Practical method
- 9.2.2 Automatic method
- 9.2.2.1 General
- 9.2.2.2 Parameter for detecting breakdown
- 9.2.2.3 Determination of the criteria for breakdown
- 9.2.2.4 Determination of the point at which breakdown can be assumed to have occurred
- 9.3 Determination of changes in specific parameters
- 9.3.1 Temperature rise
- 9.3.2 Creep
- 9.3.3 Compression set
- 9.3.4 Dynamic properties

10 Precision

11 Test report

Annex A (informative) Precision

- A.1 General
- A.2 Precision details
- A.3 Precision results
- A.4 Usage of precision results

Annex B (normative) Calibration schedule

B.1 Inspection
B.2 Schedule

Page count: 20