ISO 21813:2019 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) — Methods for chemical analysis of high purity barium titanate powders

Contents

Foreword

1 Scope

2 Normative references

3 Terms and definitions

4 Analytes and ranges

5 Preparation of test sample

5.1 General
5.2 Sampling
5.3 Drying
5.4 Weighing

6 Reporting the analytical values

6.1 Number of analyses
6.2 Blank test
6.3 Evaluation of the analytical values
6.4 Expression of the analytical values

7 Determination of the barium and titanium contents

7.1 Classification of the determination methods
7.2 Acid decomposition-gravimetric method
7.2.1 Principle
7.2.2 Reagents
7.2.3 Apparatus
7.2.4 Procedure
7.2.5 Blank test
7.2.6 Calculation
7.3 Acid decomposition-ICP-OES method
7.3.1 Principle
7.3.2 Reagents
7.3.3 Apparatus
7.3.4 Procedure
7.3.5 Blank test
7.3.6 Drawing of the calibration curve
7.3.7 Calculation

8 Determination of the trace element contents

8.1 Principle
8.2 Reagents
8.3 Apparatus
8.4 Procedure
8.5 Blank test
8.6 Drawing of the calibration curve
8.7 Calculation

9 Determination of the total nitrogen content

9.1 Principle
9.2 Reagents
9.3 Apparatus

9.4 Instrument
9.5 Procedure
9.5.1 Starting up of the instrument
9.5.2 Preliminary heating
9.5.3 Degassing of the graphite crucible
9.5.4 Measuring
9.6 Blank test
9.7 Calculation of the calibration coefficient
9.8 Calculation

10 Determination of the oxygen content

10.1 Principle
10.2 Reagents
10.3 Apparatus
10.4 Instrument
10.5 Procedure
10.6 Blank test
10.7 Calculation of the calibration coefficient
10.8 Calculation

11 Determination of the carbon content

11.1 Classification of the determination methods
11.2 Combustion (resistance furnace)-IR absorption spectrometry
11.2.1 Principle
11.2.2 Reagents
11.2.3 Apparatus
11.2.4 Instrument
11.2.5 Procedure
11.2.5.1 Stabilization of the instrument
11.2.5.2 Mixture of the sample and combustion accelerators
11.2.5.3 Sample combustion
11.2.5.4 Measurement
11.2.6 Blank test
11.2.7 Calculation of the calibration coefficient
11.2.8 Calculation
11.3 Combustion (radio frequency heating furnace)-thermal conductometry
11.3.1 Principle
11.3.2 Reagents
11.3.3 Apparatus
11.3.4 Instrument
11.3.5 Procedure
11.3.5.1 Stabilization of the instrument
11.3.5.2 Mixture of the sample and combustion accelerators
11.3.5.3 Sample combustion
11.3.5.4 Measurement
11.3.6 Blank test
11.3.7 Calculation of the calibration coefficient
11.3.8 Calculation
11.4 Combustion (radio frequency heating furnace)-IR absorption spectrometry
11.4.1 Principle
11.4.2 Reagents
11.4.3 Apparatus
11.4.4 Instrument
11.4.5 Procedure
11.4.5.1 Stabilization of the instrument
11.4.5.2 Mixture of the sample and combustion accelerators
11.4.5.3 Sample combustion
11.4.5.4 Measurement
11.4.6 Blank test
11.4.7 Calculation of the calibration coefficient
11.4.8 Calculation

12 Test report

Annex A (informative) Analytical results obtained from the round-robin test