ISO 21432:2019-12 (E)

Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction

Contents

Page

Foreword v

Introduction vii

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Symbols and abbreviated terms 5
4.1 Symbols and units 5
4.2 Subscripts 7
4.3 Abbreviated terms 7

5 Summary of method 7
5.1 General 7
5.2 Outline of the principle -- Bragg's law 7
5.3 Neutron sources 7
5.4 Strain determination 8
5.4.1 General 8
5.4.2 Monochromatic instrument 8
5.4.3 TOF instrument 8
5.5 Neutron diffractometers 9
5.6 Stress determination 9

6 Purpose, geometry and material 14
6.1 General 14
6.2 Purpose of the measurement 14
6.3 Geometry 14
6.4 Composition 14
6.5 Thermal/mechanical history 15
6.6 Phases and crystal structures 15
6.7 Homogeneity 15
6.8 Microstructure 15
6.9 Texture 15

7 Preparations for measurements 15
7.1 General 15
7.2 Alignment and calibration of the instrument 15
7.3 Choice of diffraction conditions 16
7.3.1 Monochromatic instruments 16
7.3.2 TOF instruments 18
7.4 Positioning procedures 19
7.5 Gauge volumes 19
7.6 Methods for establishing the macroscopically stress-free or reference lattice spacing 20

8 Measurement and recording requirements 22
8.1 General 22
8.2 Recording requirements 22
8.2.1 General 22

8.2.2 General information -- instrument 22
8.2.3 General information -- specimen 23
8.2.4 Specific information required for each diffraction measurement 23
8.3 Specimen co-ordinates 24
8.4 Positioning of the specimen 24
8.5 Measurement directions 24
8.6 Number and location of measuring positions 24
8.7 Gauge volume 25
8.8 Gauge volume centroid considerations 25

8.9 Temperature 25

9 Calculation of stress 25
9.1 General 25
9.2 Normal stress determinations 25
9.3 Stress state determinations 26
9.3.1 General 26
9.3.2 The sin2 method 26
9.4 Choice of elastic constants 27
9.5 Diffraction data analysis 27
9.5.1 General 27
9.5.2 Peak fitting function 27
9.5.3 Background function 28
9.5.4 Peak to background ratio 28
9.5.5 Distorted peak profiles 28

10 Reliability 29

11 Reporting 30
11.1 General 30
11.2 Strain or stress values 30
11.2.1 General 30
11.2.2 Stress-free or reference lattice spacing 30
11.2.3 Conversion of strain to stress 30
11.2.4 Elastic constants 30
11.2.5 Positioning 30
11.3 Neutron source and instrument 30
11.4 General measurement procedures 31
11.5 Specimens/materials properties 31
11.6 Original data 31
11.7 Uncertainties and errors 31

Annex A (informative) Measurement and analysis methodologies 32

Annex B (informative) Determination of uncertainties in a measurand 41

Bibliography 44