DIN EN ISO 21432:2021-05 (E)

Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction (ISO 21432:2019)

Contents

Page

European foreword ... **4**

Foreword ... **5**

Introduction ... **7**

1 Scope ... **8**

2 Normative references ... **8**

3 Terms and definitions ... **8**

4 Symbols and abbreviated terms ... **12**
4.1 Symbols and units ... 12
4.2 Subscripts ... 14
4.3 Abbreviated terms ... 14

5 Summary of method ... **14**
5.1 General ... 14
5.2 Outline of the principle — Bragg's law ... 14
5.3 Neutron sources ... 14
5.4 Strain determination ... 15
5.4.1 General ... 15
5.4.2 Monochromatic instrument ... 15
5.4.3 TOF instrument ... 15
5.5 Neutron diffractometers ... 16
5.6 Stress determination ... 16

6 Purpose, geometry and material ... **21**
6.1 General ... 21
6.2 Purpose of the measurement ... 21
6.3 Geometry ... 21
6.4 Composition ... 21
6.5 Thermal/mechanical history ... 22
6.6 Phases and crystal structures ... 22
6.7 Homogeneity ... 22
6.8 Microstructure ... 22
6.9 Texture ... 22

7 Preparations for measurements ... **22**
7.1 General ... 22
7.2 Alignment and calibration of the instrument ... 22
7.3 Choice of diffraction conditions ... 23
7.3.1 Monochromatic instruments ... 23
7.3.2 TOF instruments ... 25
7.4 Positioning procedures ... 26
7.5 Gauge volumes ... 26
7.6 Methods for establishing the macroscopically stress-free or reference lattice spacing ... 27

8 Measurement and recording requirements ... **29**
8.1 General ... 29
8.2 Recording requirements ... 29

8.2.1 General 29
8.2.2 General information — instrument 29
8.2.3 General information — specimen 30
8.2.4 Specific information required for each diffraction measurement 30
8.3 Specimen co-ordinates 31
8.4 Positioning of the specimen 31
8.5 Measurement directions 31
8.6 Number and location of measuring positions 31
8.7 Gauge volume 32
8.8 Gauge volume centroid considerations 32
8.9 Temperature 32
9 Calculation of stress 32
9.1 General 32
9.2 Normal stress determinations 32
9.3 Stress state determinations 33
9.3.1 General 33
9.3.2 The $\sin^2\psi$ method 33
9.4 Choice of elastic constants 34
9.5 Diffraction data analysis 34
9.5.1 General 34
9.5.2 Peak fitting function 34
9.5.3 Background function 35
9.5.4 Peak to background ratio 35
9.5.5 Distorted peak profiles 35
10 Reliability 36
11 Reporting 37
11.1 General 37
11.2 Strain or stress values 37
11.2.1 General 37
11.2.2 Stress-free or reference lattice spacing 37
11.2.3 Conversion of strain to stress 37
11.2.4 Elastic constants 37
11.2.5 Positioning 37
11.3 Neutron source and instrument 37
11.4 General measurement procedures 38
11.5 Specimens/materials properties 38
11.6 Original data 38
11.7 Uncertainties and errors 38
Annex A (informative) **Measurement and analysis methodologies 39**
Annex B (informative) **Determination of uncertainties in a measurand 48**
Bibliography 51