DIN EN ISO 12807:2021-05 (E)

Safe transport of radioactive materials - Leakage testing on packages (ISO 12807 :2018)

Contents

Page

European foreword ... **4**

Foreword ... **5**

Introduction ... **6**

1 Scope ... **7**

2 Normative references ... **7**

3 Terms and definitions ... **7**

4 Symbols and units ... **10**

5 Regulatory requirements ... **13**
5.1 Relevant regulations ... 13
5.2 Regulatory containment requirements ... 13

6 Procedure for meeting the requirements of this document ... **13**
6.1 General ... 13
6.2 Quality management system ... 14
6.3 Procedure ... 14
6.3.1 General ... 14
6.3.2 Determination of permissible activity release rates ... 15
6.3.3 Determination of standardized leakage rates ... 16
6.3.4 Determination of permissible test leakage rates for each verification stage ... 16
6.3.5 Selection of appropriate test methods ... 16
6.3.6 Performance of test and record of results ... 16

7 Determination of permissible activity release rates ... **16**
7.1 Step 1: List the radioactive contents, A_i ... 16
7.2 Step 2: Determine the total releasable activity, RI_T ... 16
7.3 Step 3: Determine the maximum permissible activity release rates, R ... 17

8 Determination of standardized leakage rates ... **17**
8.1 General ... 17
8.2 Step 4: Determine the activity release rate due to permeation, RP ... 18
8.3 Step 5: Determine the maximum permissible activity release rate due to leakage, RG ... 18
8.4 Step 6: Determine the activity per unit volume of the containment system medium, C ... 18
8.5 Step 7: Determine the maximum permissible volumetric leakage rate of the medium, L ... 18
8.6 Step 8: Determine the maximum permissible equivalent capillary leak diameter, D ... 18
8.7 Step 9: Determine the permissible standardized leakage rate, Q_{SLR} ... 19

9 Containment-system verification requirements ... **19**
9.1 Containment-system verification stages ... 19
9.1.1 General ... 19
9.1.2 Design verification ... 20
9.1.3 Fabrication verification ... 20
9.1.4 Preshipment verification ... 20
9.1.5 Periodic verification ... 21
9.1.6 Maintenance verification ... 21
9.2 Verification requirements ... 21
9.2.1 General ... 21
9.2.2 Step 10: Determine permissible test leakage rate for each verification stage, Q_{TDA}, Q_{TDN}, Q_{TF}, Q_{TS}, Q_{TP} and Q_{TM} ... 21
9.2.3 Step 11: Select appropriate test methods ... 21

10 Leakage test procedure requirements **22**
10.1 General 22
10.2 Step 12: Perform tests and record results 22
10.3 Test sensitivity 22
10.4 Test procedure requirements 22
10.4.1 General 22
10.4.2 Testing 22
Annex A (informative) **Preferred leakage test methods** **23**
Annex B (informative) **Methods of calculation** **37**
Annex C (informative) **Conversion tables** **42**
Annex D (informative) **Worked examples** **43**
Annex E (informative) **Rationale** **78**
Bibliography **91**