ISO 3892:2000-06 (E)

Conversion coatings on metallic materials - Determination of coating mass per unit area - Gravimetric methods

Contents

Page

Foreword iv

1 Scope 1

2 Apparatus 1

3 Test pieces 2

4 Reagents and procedures 2
4.1 General 2
4.2 Phosphate coatings on iron and steel 2
4.3 Phosphate coatings on zinc and cadmium 3
4.4 Crystalline phosphate coatings on aluminium and its alloys 3
4.5 Chromate coatings on zinc and cadmium 4
4.6 Chromate and amorphous phosphate coatings on aluminium and its alloys 4

5 Expression of results 5
5.1 Calculation 5
5.2 Measurement uncertainty 5