ISO 4259-4:2021-12 (E)

Petroleum and related products - Precision of measurement methods and results - Part 4: Use of statistical control charts to validate ' in-statistical-control' status for the execution of a standard test method in a single laboratory

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms,definitions,symbolsandabbreviatedterms 1
3.1 Specific terms and definitions 2
3.2 Symbols and abbreviated terms 2

4 Statistical control in the execution of a standard test method by a laboratory 3
4.1 General 3
4.2 Control chart description 4
4.2.1 General 4
4.2.2 I- and MR-charts 4
4.2.3 I-chart sensitivity enhancement strategy 4
4.2.4 In-statistical-control conditions 5
4.3 Control chart work process 5
4.3.1 General 5
4.3.2 Stage 1 of control chart work process 5
4.3.3 Stage 2 of control chart work process 9
4.4 QC material batch change transition 11
4.4.1 General 11
4.4.2 Procedure 1, concurrent testing 12
4.4.3 Procedure 2, Q-chart 12
4.4.4 Procedure 3, dynamically updated I-chart with EWMA 12

5 Guidanceforinsufficientvariationornon-normaldata 13
5.1 General requirement 13
5.2 How to deal with insufficient variation or non-normal data 13
5.2.1 Insufficient variation 13
5.2.2 Non-normal data 14

Annex A (informative) Details of the control chart work process 15

Annex B (normative) Check procedures 34

Bibliography 36