ISO 1352:2021-12 (E)

Metallic materials - Torque-controlled fatigue testing

Contents

Page

Foreword ..... **v**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Symbols and abbreviated terms **3**

5 Principle of test **4**

6 Test plan **5**

7 Shape and size of specimen **5**
7.1 Form 5
7.2 Dimensions 7
7.2.1 Specimens of circular cross-section 7
7.2.2 Specimens with tubular cross-section 8

8 Preparation of specimens **8**
8.1 General 8
8.2 Machining procedure 8
8.3 Sampling and marking 9
8.4 Surface conditions of specimen 9
8.5 Dimensional checks 10
8.6 Storage and handling 10

9 Apparatus **10**
9.1 Testing machine 10
9.1.1 General 10
9.1.2 Torque cell 10
9.1.3 Gripping of specimen 11
9.1.4 Alignment check 11
9.1.5 Axial force 11
9.2 Heating system 12
9.3 Instrumentation for test monitoring 12
9.3.1 Recording system 12
9.3.2 Cycle counter 12
9.3.3 Checking and verification 13

10 Test procedure **13**
10.1 Mounting of specimen 13
10.2 Frequency of testing 13
10.3 Heating for the isothermal elevated temperature test 13
10.4 Application of torque 13
10.5 Calculation of nominal torsional (shear) stress 13
10.6 Recording of temperature and humidity 14
10.7 Failure and termination criteria 14
10.7.1 Failure 14
10.7.2 Termination 14

11 Measurement uncertainty **14**

12 Test report **15**

Annex A (informative) **Presentation of results** **16**

Annex B (informative) **Verification of alignment of torsional fatigue testing machines** **20**
Annex C (informative) **Measuring uniformity of torsional strain (stress) state** **22**
Annex D (informative) **Estimation of measurement uncertainty** **25**
Bibliography **27**