DIN CEN/TS 18094:2025-02 (E)

Non-destructive testing - Test method for determining residual stresses by synchrotron x-ray diffraction; English version CEN/TS 18094:2024

Contents

Page

European foreword 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Symbols and abbreviated terms 11
4.1 Symbols and units 11
4.2 Subscripts 12
4.3 Abbreviations 12

5 Summary of the synchrotron XRD measurement method 12
5.1 General 12
5.2 Diffraction techniques 14
5.2.1 General information 14
5.2.2 Effects due to the material structure 15
5.3 Synchrotron high energy X-ray diffraction 16
5.3.1 General 16
5.3.2 Monochromatic beam for angle-dispersive X-ray diffraction (ADXRD) 16
5.3.3 Polychromatic beam for energy-dispersive X-ray diffraction (EDXRD) 17
5.4 Residual stress calculation 17
5.4.1 Strain 17
5.4.2 Stress 19
5.5 Sources of error and uncertainty 21
5.5.1 Errors and misapplications 21
5.5.2 Uncertainties 22

6 Preparation of measurement and calibration 23
6.1 Sample preparation 23
6.1.1 General 23
6.1.2 Geometry 23
6.1.3 Composition 23
6.1.4 Thermal/mechanical history 24
6.1.5 Phases and crystals 24
6.1.6 Homogeneity, microstructure and texture 24
6.1.7 Grain size 24
6.2 Instrumentation preparation 24
6.2.1 Instrumentation calibration 24
6.2.2 Verification of the instrumentation 24
6.3 Experimental setup 25
6.3.1 Choosing the measurement method and beam type 25
6.3.2 Reflection geometry 25
6.3.3 Transmission geometry 25
6.3.4 Energy-dispersive (EDXRD) mode 25
6.3.5 Angle dispersive (ADXRD) mode 25
6.3.6 Determination of the gauge volume (GV) 26
6.3.7 Peak selection 26

6.3.8 Temperature 27
6.4 Measurement procedure: EDXRD – transmission 27
6.4.1 General considerations 27
6.4.2 Calibration of the detector 27
6.4.3 Instrument alignment 27
6.4.4 Calibration of scattering angle 27
6.5 Measurement procedure: EDXRD – reflection 28
6.5.1 General considerations 28
6.5.2 Calibration of detector 28
6.5.3 Instrument alignment 28
6.5.4 Calibration of scattering angle 28
6.5.5 Determination of gauge volume (GV) 28
6.5.6 Sample positioning 29
6.5.7 Slit positioning 29
6.6 Measurement procedure: ADXRD – transmission and reflection 29
6.6.1 General considerations 29
6.6.2 Calibration of detector 29
6.6.3 Instrument alignment 30
6.6.4 Calibration of scattering angle 30
6.6.5 Detector distance 30
6.6.6 Defining beam parameters 30
6.6.7 Performing the measurement 31
6.7 Measurement procedure: ADXRD – CSC 31
6.7.1 General considerations 31
6.7.2 Calibration of detector 31
6.7.3 Instrument alignment 31

7 Measurement and recording requirements 31
7.1 General 31
7.2 Measurements 31
7.3 Recording requirements 32
7.4 Reduction of measurement data and data fitting 32

8 Data analysis and stress calculation 33
8.1 Specific equations for synchrotron radiation-based diffraction techniques 33
8.1.1 General 33
8.1.2 Data input 33
8.1.3 Stress-free reference input 34
8.1.4 Strain calculation 34
8.1.5 Elastic constant input 34
8.1.6 Stress calculation 34
8.2 Evaluation of uncertainty in the measurement 35
8.2.1 Random and systematic uncertainties 35
8.2.2 Interlaboratory comparison 36
8.3 Description of the final residual stress data output format 36

9 Reporting 37

Annex A (informative) Reference samples 38

Annex B (informative) Harmonization of data structures 41

Bibliography 47