ISO 25086-1:2026-01 (E)

Textiles - Determination of the snagging resistance of fabrics - Part 1: Mace (spiked ball) test method

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 1

5 Apparatus 2

6 Pre-treatment of fabric 4

7 Atmosphere for conditioning and testing 4

8 Preparation of test specimens 4

9 Procedure 5

9.1 Mounting of the felt 5

9.2 Checking and adjustment of the mace (spiked ball) 5

9.3 Setting of the testing time 6

9.4 Test specimen mounting 6

9.5 Testing running 6

10 Assessment of snagging 6

11 Test report 7

Bibliography 9