ISO 9348:2026-05 (E)

Textiles - Determination of the anti-contamination propensity of fabrics to particulate matter - Digital measurement method

Contents

Page

Foreword ..... **iv**

Introduction ..... **v**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Principle **2**

5 Apparatus and material **2**

6 Conditioning and testing atmosphere **4**
6.1 Test particle conditioning 4
6.2 Test atmosphere and conditioning 4

7 Preparation of test **4**
7.1 Test specimens 4
7.2 Test specimen canister 4

8 Procedure **5**

9 Assessment **5**
9.1 Image acquisition method 5
9.2 Image acquisition procedure 5
9.3 Image analysis 5
9.4 Calculation and expression of results 6

10 Test report **6**

Annex A (informative) **Test particle** **7**

Bibliography **8**